

	Type	L #	Hits	Search Text	DBs	Time Stamp	Com men ts	Er ro rs
1	BRS	L 1	63	gordon.xa. and piezoelectric\$5	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 5 23:58		0
2	BRS	L 2	2	4523199.pn.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 5 23:59		0
3	BRS	L 3	7	4523199.URPN.	USPA T	2004/06/2 5 23:59		0
4	BRS	L 4	10	("4045801" "4068144" "4146901" "4199770" "4228440" "4231047" "4241406" "4291316" "4389657" "4395719").PN.	USPA T	2004/06/2 5 23:59		0
5	BRS	L 5	2	4395719.pn.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:00		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errors
6	BRS	L 6	24	4395719.URPN.	USPA T	2004/06/25 23:59		0
7	BRS	L 7	17	("3215078" "3683212" "3781955" "3787884" "3832579" "3840758" "3848118" "3864696" "3924974" "3946398" "3972474" "4027308" "4068144" "4115036" "4146899" "4228440" "4251824").PN.	USPA T	2004/06/25 23:59		0
8	BRS	L 8	1	(2 5) and (glass or quartz)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/26 00:02		0
9	BRS	L 9	55	3 4 6 7	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/26 00:02		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r s
10	BRS	L 2 6	0	wo9748557.did.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:38		0
11	BRS	L 2 7	3	9748557.did.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:41		0
12	BRS	L 2 8	1	6164850.pn. and glass	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:45		0
13	IS&R	L 2 9	6	(("4228440") or ("4231047") or ("4499479") or ("4822250") or ("4199770") or ("4520374")) .PN.	USPA T	2004/06/2 6 00:44		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Com men ts	E r r o r s
14	BRS	L 3 0	2	29 and glass	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:44		0
15	BRS	L 3 1	1	6164850.pn. and (simultaneous\$2)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:57		0
16	BRS	L 3 2	2	29 and (simultaneous\$2)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:49		0
17	BRS	L 3 3	3	(6164850.pn. or 29) and (driver\$1)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 6 00:57		0